

GENERAL INFOR	MATION												
_	PLAINT 🗌	RECONNA		_		U FOLL		□ ОРЕ	RAT	OR REQUEST		OTHER	
FACILITY NAME (LLC, Inc., Corp, Partnership, sole proprietorship, etc.) VB Family Farms Glen Von Bokel INSPECTION DATE 12-20-12						ARRIVAL TIME 8:45AM							
						INSPECTO Brian Ro				DEPARTURE TIME 10:15AM			
CITY Carlyle				STATE IL			DE		CCOMPANIED BY (if applicable) ruce Rodely				
COUNTY SECTION TOWNSH Clinton 25 3N						TICAL eatfield	TICAL TOWNSHIP atfield		TEMPERATURE 46F		PRECIPITATION TYPE 2" last 24		PΕ
Facility Owner(s): Exemption 6 and Exemption 7(C)	NAME Glen Von Be	okel					CON YES	TACTED S		ONE emption 6		OBILE I Exemption 7	'(C)
	ADDRESS					CITY				STATE	ZIF	CODE	
	NAME						CONTA		PH	ONE		MOBILE	
	ADDRESS					CITY				STATE	ZIF	CODE	
Facility Operator(s):	NAME						CONTA		PH	ONE		MOBILE	
Exemption 6 and Exemption 7(C)	ADDRESS					CITY				STATE	ZIF	CODE	
,	NAME						CONT	TACTED S	PH	ONE	•	MOBILE	
	ADDRESS					CITY			•	STATE	ZIF	CODE	
NPDES PERMIT	INFORMAT	TION (If	no	NPDES	Per	mit, sl	cip th	is sectio	n)				
1. What type of N Individual	NPDES perm NPDES Peri		en is	_	ener	al NPDI	ES Per	mit				NPDES #	
2. What date was		•											
3. What date doe				ire?								LVEC III NO	
4. Is a copy of the NPDES permit onsite?5. Permitted number of animals (no. & specie)?													
		•			ched	ule?					П	YES NO)
6. Does the NPDES Permit contain a compliance schedule? 7. Have there been any changes made to the production area since the permit was issued? 7. YES NC													
If "YES", provi	de a detailed	d descript	tion	of those	e cha	nges.		•				1	
None													

Facility Name: **VB Family Farms Glen Von Bokel** Inspection Date: **12-20-12** Page 2/8

LAND APPLICATION/NUTRIENT MANAGEMENT		
How many TOTAL acres are available for land application? 843 acres		
2. How many acres are READILY available for land application at the time of inspection?	443	acres
3. Estimated annual quantities of liquid waste gallons		
4. Estimated annual quantities of solid waste tons		
5. Does the facility have a contractor perform land application? If "YES", Name of Contractor: Harke or Metro Ag	⊠ YES	□ NO
6. What type of land application equipment is available to the facility?		
 ✓ Umbilical Injection ✓ Honeywagon Injection ☐ Honeywagon Surface ☐ Irrig ☐ Rotational Gun ☐ Manure Spreader ☐ Vegetative Filter ☐ Other 	jation	
7. Does the facility calibrate the land application equipment? If "YES", What method is used? Manufacturer Recommendations		□ NO
8. Does the facility land apply within the 150 foot setback from any water well? If "YES", Explain	☐ YES	⊠ NO
9. Does the facility land apply within the 200 foot setback from any surface water? If "YES", Explain	☐ YES	⊠ NO
10. Does the facility land apply near any residences? If "YES", Explain Neighbor to field.		□ NO
11.Is livestock waste transferred off-site to another party? If "YES", Are records of manure transfers kept? If "YES", Ask to see records		□ NO □ NO
12. Does the facility have a current NMP or CNMP? If "YES", Does the facility maintain a copy of the nutrient management plan (NMP) onsite?		□ NO □ NO
13. Does the NMP reflect the current operational characteristics (number of animals, cropping, etc.)?	⊠ YES	□ NO
14. Are the number of acres owned/leased consistent with those in the NMP?		□ NO
15.Is manure and wastewater being applied in accordance with setback/buffer requirements of the NMP?		□ NO
16. Are all of the records identified in the NMP being maintained and kept current?		☐ NO
17. Are records being maintained at the required frequency?		□ NO
18. Are records being maintained onsite for the period required by NMP and/or NPDES permit?	☐ YES	⊠ NO
19. Is the NMP adequately addressing the storage, handling and application of manure and wastewater to prevent discharges to waters of the U.S.?		□ NO

Facility Name: **VB Family Farms Glen Von Bokel** Inspection Date: **12-20-12** Page 3/8

LIV	ESTOCK FACILITY DESCRIPT	ION						
Туре	e of Animals	Number of Animals (currently)	Animal Capacity	Type of Confineme	ent	Nun Stru		r of ires
DAIR	RY MILKING	325	450	TOTAL CONFINEME	NT BDG	4		
DAIR	RY DRY	90	Unknow	OPEN CONCRETE FE	EDLOT	1		
CALV	/ES	30	50	OTHER (Specify)	Calf Huts	50		
If gre	the facility have an Illinois Certifie eater than 1000 animal units but e management plan?				•	YES		NO NO
If gre	eater than 5000 animal units, has A for review?	the facility su	ibmitted a w	vaste management pla	an to N/A	YES		NO
manı	s the facility have any other locatiure is shared, or where the other esses below.				•	YES		NO
LIV	ESTOCK WASTE STORAGE							
1.	Does the facility have any exist If NO, then proceed to question	_	vaste contai	nment system?	YES NO			
2.	General description of the wast feed storage areas). Settling basin, gravity overf		,	·			•	and

Facility Name: VB Family Farms Glen Von Bokel Inspection Date: 12-20-12 Page 4/8 Type of Storage **Total Storage Capacity (Specify Units)** Anaerobic Lagoon Covered Lagoon 1st104X100X15 & 2nd205X265X20(1.1 & 8.1 million gal.) Molding Pond Above Ground Storage Tank ("Slurrystore") Below Ground Storage Tank 118X100X4 (0.35 million gallons) Settling Basin Roofed Storage Shed Concrete Pad Impervious Soil Pad Underfloor Pits Anaerobic Digester Manure Stacks → Vegetative Filter Other None Do the storage structures have depth markers or staff gauges? X YES NO Are levels of manure in the storage structures recorded and records kept?
YES \bowtie NO 5. Do the storage structures have adequate freeboard?

YES \bowtie NO Estimated final stage storage structure freeboard 40 in. of total depth 240 in. 7. Do facility personnel perform routine visual inspections of the storage structures?

YES NO 8. Are the routine visual inspections documented?

YES \bowtie NO \bowtie NO Does the system have an outfall or discharge point? \(\simega\) YES If "YES", please provide a description (overflow pipe, spill way, etc. Include a description the area receiving the discharge). **None** 10. Are there any portions of the production area where runoff is not controlled? X YES l l NO If "YES", provide a detailed description of the area(s) of concern:

Silage bunker draining out of the northwest corner (see photo pages). **MORTALITIES MANAGEMENT** 1. How are mortalities managed? (Composted, buried, burned, rendering service, other) Rendered or buried.

Are mortalities documented and are records kept? XES

2.

Facility Name: **VB Family Farms Glen Von Bokel** Inspection Date: **12-20-12** Page 5/8

FAC	ILITY WATER SOURCES
1.	What type of method is used to provide drinking water for the animals?
	☐ Overflow waters ☐ Tip Tanks ☐ Nipple waters ☐ Water Bowls ☐ Other
2.	How is the water for animals obtained? ☐ Community PWS ☐ On-Site Well ☐ On-Site Impoundment ☐ Other
3.	Is a mist cooling system used? ✓ YES ✓ NO How is mist water contained? Collection Basin.
DAI	RY OPERATION (If No Dairy, skip this section)
1.	How many times per day are cows milked? 2
2.	Describe how the dairy's non-contact cooling water is contained (Example: it is reused for drinking water for the animals). Used for drinking water.
3.	Describe how the milking parlor is cleaned (hose or flush) and where the process wastewater goes and how it is contained. Manually hosed to the collection basin.
4.	Describe how the tank(s) are washed and where the process wastewater goes and how it is contained. Automatically washed to the collection basin.
5.	Describe where process wastewater from the plate cooler goes and how it is contained. Drinking water.
BEC	DDING (If No Bedding, skip this section)
1.	Describe what type of bedding is used for the animals. Sand.
2.	Describe how bedding is collected and how often. Attrition by animal foot traffic.
3.	What is done with the used bedding? Reused Land Applied

Facility Name: VB Family Farms Glen Von Bokel Inspection Date: 12-20-12 Page 6/8 **MANURE COLLECTION** How is manure collected? ☐ Under Floor Pit ☐ Scraped: ☐ Automatic ☐ Manual ☐ Flush ☐ Solids Separator Other: _____ None If manure collection system uses either clean or reused water to flush, describe where this water goes and how it is contained. None FEED STORAGE CONTAINMENT Describe how feed (silage, hay, etc) is contained. ☐ Bulk Bins ⊠ Silage Pit ☐ Ag Bags ☐ Hay: ☐ Barn Outdoor Other: Silage Bags Describe how feed (silage, hay, etc) runoff is contained. ■ Not Applicable – Feed totally enclosed ⊠ None **RECEIVING SURFACE WATERS** 1. Provide a description of the flow path from the facility to the nearest named surface water. Unnamed tributary and overland flow 1/2 mile northwest to Flat Branch. 2. What is the name of the receiving stream? **Unnamed tributary.** 3. Status of the named surface water:

Intermittent Perennial 4. Are any unnatural bottom deposits observed in the receiving stream: \(\sum \) YES \(\sim \) NO

If "YES", provide a description of the deposits: **None**

Facility Name: VB Family Farms Glen Von Bokel Inspection Date: **12-20-12** Page 7/8 **DISCHARGES** 1. Have there been any documented discharges of livestock waste to surface water *in the* | NO past year? If "NO" proceed to guestion 2. a. If "YES", specify the date(s). _5/01/12_ b. What was the reason for the discharge? Lack of containment for feedlot and both ends of the silage bunker. Was the discharge the result of a 25 year-24 hour rainfall event? YES M NO d. What was the precipitation amount? (if applicable) Was IEMA notified of the discharge? YES NO ⊠ YES NO Has the facility taken corrective action to remedy the situation which caused the discharge(s)? If "YES", describe actions taken: The south end of the silage bunker and eastern feedlot is diverted to a grating that drains to the waste storage system. Part of the south end of the eastern feedlot is also discontinued. Grading has been completed for a new barn in effort to discontinue eastern feedling operation. 2. Is the facility currently discharging livestock waste from the production area? If "NO" NO proceed to next section. Was the discharge the result of a 25 year-24 hour rainfall event? YES NO b. What was the precipitation amount? (if applicable) c. What is the reason for the discharge? Uncontrolled silage leachate from the northwest end of the silage bunker. d. Were water quality samples taken? YES M NO e. If "YES", how many? N/A What parameter(s) tested?

pH **Nitrite** Ammonia Nitrate **Phosphorus** BOD₅ Total Susp Solids Fecal Diss O₂ Other **BIOSECURITY – Inspection Activities** 1. Were biosecurity measures discussed with the facility prior to inspection? NO 2. Has there been 24-hours downtime between inspections for all IEPA personnel present? ⊠ YES NO 3. Was the order of inspection conducted from high risk to low risk? YES NO 4. Did all personnel stay outside livestock management and livestock waste handling facilities |X| YES NO as defined in 35 IAC 501.285 and 35 IAC 501.300? If "YES" skip to question 7. **BIOSECURITY – Personal Protection Equipment** 5. Was sanitary footwear donned prior to entering the livestock N/A NO management/waste handling facility(s)? Did not Enter

 \square N/A

Did not Enter

YES

NO

NO

NO

6. Were disposable coveralls donned prior to entering the livestock

8. Was disposable sanitary outerwear disposed at the facility?

management/waste handling facility(s)?

7. Was sanitary footwear used during the inspection?

BIOSECURITY - Vehicle 9. Was the vehicle parking location discussed with the facility prior to inspection? NO 10. Was the vehicle washed since the inspection prior to current? If "YES" skip to question 12. YES \boxtimes NO 11. Was the vehicle parked >300-feet from the livestock management/waste \bowtie NO N/A YES handling facility? Explain where vehicle was parked: 12. Was IEPA vehicle used on site? NO 13. Was facility vehicle used on site? ☐ YES \bowtie NO **BIOSECURITY – Inspection Equipment** 14. Was all equipment wiped down with anti-bacterial wipes? NO 15. Was sample cooler kept inside vehicle during inspection? If "YES" skip guestion 16. NO 16. Was sample cooler wiped down with antibacterial wipes before placing back into N/A ☐ YES vehicle? **OTHER COMMENTS/NOTES** See attached photo pages concerning the discussion to follow. We met with VonBokel in the gravel parking area he directed us to park and completed the Livestock Facility Inspection Checklist. We toured the facility observing the silage bunker, silage bags, feedlots, waste handling system, and the site prepared for a new barn. Silage leachate was noted discharging out of the north west corner of the silage bunker, runing south along the silage bags, and reporting to the ditch where a sample was previously taken on 5/01/12. The ditch drains southwesterly to an unnamed tributary that discharges to an unnamed tributary to Flat Branch. Diversions have been implemented on the south end of the silage bunker to direct leachate to a grating that reports to the waste handling system. No other discharges were noted at the time of inspection. No samples were taken due to lab scheduling. VonBokel was advised to contain the silage leachate out of the north end of the silage bunker. VonBokel indicated that he thought the only thing anyone was worried about was the leachate from the south end. I told VonBokel that the VN letter had recommendations to contain the silage leachate from all silage storage and he may want to consider a reception pit designed to deliver the leachate to the waste handling system. VonBokel indicated that he would work on a containment system for the silage leachate. Check all attachments: Narrative N Photos Site Plan Sample Results **INSPECTOR'S SIGNATURE** REPORT DATE 12/28/12 Cc: BOW/DWPC/RU Attachments:

Facility Name: VB Family Farms Glen Von Bokel

Revised March 2012

Inspection Date: 12-20-12

Page 8/8